


QUICK START GUIDE


for building the

Protobot





[5/64"]x1




[3/32"]x1




[1/4"]x1

1



[SS2] 1/4" MOTOR SCREW



[SS4] 1/2" MOTOR SCREW

2



[1/4"]




[NK] 8-32 NUT KEYS




[B0.5, 1, 2, 3]

3




[5/64"]



[COL] COLLAR


4



[3/32"]




[S2] 1/4" SCREW




[S3] 3/8" SCREW

5




[BR] POP RIVETS








[BF] BEARING FLAT



6











[BF] BEARING FLAT

















10





11





12









15





16



17





20

[COL]x2



[W4]x1

[SP1]x1

[G60]x1

19

[SQ3]x1





21



10

15



[S2]x2




22




23




24




25




26a




26b




27




28




29




30




31




32




33







34





35





36**37**




39






40










42



43





44





[AT]x1
[S3]x1
[AH]x1
[NK]x1

43



top view
PROTOBOT
WIRING DIAGRAM
(not shown to scale)



bottom view
PROTOBOT
WIRING DIAGRAM
(not shown to scale)

