

ENGINE LATHE

ENGINE LATHE SAFETY

- ⇒ Safety glasses must be worn when operating a lathe.
- ⇒ Do not attempt to work on a lathe without being instructed in its safe operation.
- ⇒ Never wear loose clothing or jewelry when operating a lathe.
- ⇒ Always stop the lathe before _____ the cutting tool or taking _____.
- ⇒ Never remove cuttings or chips with your hand. Use a brush.
- ⇒ Always shut off the power supply when doing major set-ups or changing accessories on a lathe.
- ⇒ Never take heavy cuts on long slender workpieces.
- ⇒ Only one person at a time controls the operation of a lathe.
- ⇒ Never lean or lounge on a lathe.
- ⇒ Never leave a rag key in the lathe chuck.

Lean key glasses power rag
measurements jewelry instructed one
Cuts lounge brush hand loose
Adjusting heavy